

Work Order (Bid Form)

Auditor: Scott Haislip (615) 274-2565 or (615) 424-2565

WORK ORDER INFORMATION

Work Order Name: WO/10010MC1862/1

Work Order Type: Weatherization

Audit Name: 10010MC1862

CLIENT INFORMATION

Client Name: Address:

Client ID: 10010MC1862 WHITE HOUSE, TN 37188

Alt. Client ID:

AGENCY INFORMATION

Agency: Mid-Cumberland Community Action Agency Agency Phone: (615) 742-1113

Fax:

Address: P.O.Box 310, 233 Legend Drive, Suite 103

Lebanon, TN 37088-0310 Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

SITE BUILT 1990 VINYL SIDING WITH FINISHED BASEMENT 816 SQ FT

Client Name: Client ID: 10010MC1862 Alt. Client ID: Work Order (Bid Form)
Work Order Name: WO/10010MC1862/1

DOE Weatherization Assistant Version 8.6.0

Page 1 of 8

Measures

Measure 1 INST	ALL 2 SMOKE ALARM	S		Componen	ts		ı	Inspected
Comment								
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety	2 SMOKE ALARMS	Each	2					
Other Detail						_		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
	L PLUMBING PENETRA	ATIONS		Componen	ıts			Inspected
UND	L PLUMBING PENETRA ER KITCHEN SINK	ATIONS		Componen	ts			Inspected
		ATIONS		Componen	ts		,	Inspected
UND		ATIONS		Componen Estimated			Actual	Inspected
UND Comment		ATIONS Units	Qty	•		Qty		Inspected
UND Comment	ER KITCHEN SINK			Estimated	1	Qty	Actual	
UND Comment # Material / Labor	ER KITCHEN SINK Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
UND Comment # Material / Labor Other	ER KITCHEN SINK Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
UND Comment # Material / Labor Other	ER KITCHEN SINK Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
UND Comment # Material / Labor Other	ER KITCHEN SINK Description / Comment	Units Each	Qty 1	Estimated	1		Actual	
UND Comment # Material / Labor Other Other Detail	ER KITCHEN SINK Description / Comment	Units Each	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	
UND Comment # Material / Labor Other	ER KITCHEN SINK Description / Comment	Units Each	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	
UND Comment # Material / Labor Other Other Detail	ER KITCHEN SINK Description / Comment	Units Each	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	

UN	asure 3 SEAL PLUMBING PENETRATIONS UNDER BATHROOM VANITY & COMMODE SUPPLY LINE (2)			Componen	ts	Inspected		
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail						_		
			Measur	e Sub Total:			Sub Total:	
	EATHER STRIP FRONT & ORS	BACK		Componen Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Doors	WEATHER STRIP	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

	D DOOR SWEEP TO FRO	ONT & BA	CK	Componen	ts			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Doors	DOOR SWEEP	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	ULK AROUND MASTER NDOW FROM INTERIOR		M	Componen Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Windows	AIR SEALING	Each	1			y		70.07
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Measure 7 SEA	AL AROUND COMMODE	BASE		Component	ts		1	Inspecte
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	AIR SEALING	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
38,	REASE ATTIC INSULAT APPROXIMATELY 8-9" I	PRESENT		Component				Inspected
38,	APPROXIMATELY 8-9" I	PRESENT		Component Estimated			Actual	Inspected
38,	APPROXIMATELY 8-9" I	PRESENT		-		Qty		Inspected
38, Comment 861 SC	APPROXIMATELY 8-9" I	PRESENT VERIFY		Estimated	,	Qty	Actual	
38, Comment 861 SC # Material / Labor	APPROXIMATELY 8-9" I	PRESENT VERIFY <i>Unit</i> s	Qty	Estimated	,	Qty	Actual	
38, Comment 861 SQ # Material / Labor Insulation	APPROXIMATELY 8-9" I	PRESENT VERIFY <i>Unit</i> s	Qty	Estimated	,	Qty	Actual	
38, Comment 861 SQ # Material / Labor Insulation	APPROXIMATELY 8-9" I	PRESENT VERIFY <i>Unit</i> s	Qty	Estimated	,	Qty	Actual	
38, Comment 861 SQ # Material / Labor Insulation	APPROXIMATELY 8-9" I	PRESENT VERIFY Units Each	Qty 1	Estimated	,		Actual	
38, Comment 861 SQ # Material / Labor Insulation	APPROXIMATELY 8-9" I	PRESENT VERIFY Units Each	Qty 1	Estimated Unit Cost	,		Actual Unit Cost	
38, Comment 861 SC # Material / Labor Insulation Other Detail	APPROXIMATELY 8-9" I	PRESENT VERIFY Units Each	Qty 1	Estimated Unit Cost	,		Actual Unit Cost	
38, Comment 861 SC # Material / Labor Insulation Other Detail	APPROXIMATELY 8-9" I	PRESENT VERIFY Units Each	Qty 1	Estimated Unit Cost	,		Actual Unit Cost	

	TALL ENERGY LID TO A VN STAIRS	ATTIC PUI	LL	Componen	ts		1	Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Other	ENERGY LID	Each	1					
Other Detail								
] []		
			Moasur	e Sub Total:] []]	Sub Total:	
			Measui	e Sub Total.]	oub rotui.	
Measure 10 MAS	TIC SEAL DUCT SYSTE	EM &		Componen	uts			Inspected
RET		EM &		Componen				Inspected
RET Comment PAN RE	URN ADINGS 4.8-10.0			Estimated	<u> </u>	Oftv	Actual	
RET Comment PAN RE # Material / Labor	URN ADINGS 4.8-10.0 Description / Comment	Units	Qty 1			Qty		Inspected
RETOMMENT PAN RE # Material / Labor Heating Equipmen	URN ADINGS 4.8-10.0 Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual	
RET Comment PAN RE # Material / Labor	URN ADINGS 4.8-10.0 Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
RETOMENT PAN RE # Material / Labor Heating Equipmen	URN ADINGS 4.8-10.0 Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
RETOMENT PAN RE # Material / Labor Heating Equipmen	URN ADINGS 4.8-10.0 Description / Comment	Units Each	Qty 1	Estimated	<u> </u>		Actual	
RETOMENT PAN RE # Material / Labor Heating Equipmen	URN ADINGS 4.8-10.0 Description / Comment	Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
RETOMMENT PAN RE # Material / Labor Heating Equipmen Other Detail	URN ADINGS 4.8-10.0 Description / Comment	Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 11 INSTALL AIR FILTER & LE HOMEOWNER	EAVE 5 FOI	₹	Componen	ts			Inspected
Comment 20" X 20"							
			Estimated	1		Actual	
Material / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Heating Equipmen AIR FILTERS	Each	1					
Other Detail							
		Measur	e Sub Total:		,	Sub Total:	
Field Notes:							
Field Notes: Measure 12 DHW TANK INSULATION Comment			Componen				Inspected
Measure 12 DHW TANK INSULATION			Estimated	<u> </u>		Actual	
Measure 12 DHW TANK INSULATION Comment Material / Labor Description / Comment	Units	Qty	-		Qty		Inspected
Measure 12 DHW TANK INSULATION	<i>Units</i> Each		Estimated	<u> </u>	Qty	Actual	
Measure 12 DHW TANK INSULATION Comment Material / Labor Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual	
Measure 12 DHW TANK INSULATION Comment Material / Labor Description / Comment Hot Water Equipm INSULATION		Qty	Estimated	<u> </u>	Qty	Actual	
Measure 12 DHW TANK INSULATION Comment Material / Labor Description / Comment Hot Water Equipm INSULATION	Each	Qty 1	Estimated	<u> </u>		Actual	

	Measure 13 DW	/H Pipe Insulation	Components						Inspected	
C	omment									
				Estimated						
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	DHW Pipe Insulation	Each	1						
2	Labor	DHW Pipe Insulation	Each	1						
(Other Detail			1			7			
L										
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									
			Work O	rder Gra	nd Total:		Gran	d Total:		